


The existing Parish Hall function is held in the school cafeteria. A new Parish hall would work for wedding receptions and other Parish related events like funeral receptions. It should also promote the development of community through “coffee & doughnuts”, adult religious education, ministries meetings and youth group meetings. I would support the development of a new Parish Hall.

Answered: 178 Skipped: 2



New Parish Hall
78.65%




Holy Family Parish Master Plan

Soderstrom Architects

I frequently have a hard time finding a place to park for weekend and Sunday Mass attendance. Parking is a problem on site. There needs to be more parking.

Answered: 179 Skipped: 1



Add Parking
54.47%




Holy Family Parish Master Plan

Soderstrom Architects

The church offices are located in the old convent building on SE Knapp street. Because the building is an old convent it doesn't work well with the current office usage. The reception area is too small and staff are remote from one another preventing effective collaboration, backup and security. The HVAC in the convent building has exceeded its anticipated life span. We should replace the parish offices with new facilities.

Answered: 179 Skipped: 1



New Office
84.92%




Holy Family Parish Master Plan

Soderstrom Architects

The Parish offices can be very difficult to find for vendors, visitors and newcomers. The school and church both have entries on SE Flavel, although the school main entry is actually on SE Cesar E. Chaves. If a new building for the offices is considered, It would make sense to locate the offices adjacent to the church entry.

Answered: 178 Skipped: 2



Move Office
67.41%




Holy Family Parish Master Plan

Soderstrom Architects

It is a challenge for the school lunch staff to share the kitchen with parish functions such as wedding and funeral receptions. A Parish only kitchen should be established.

Answered: 179 Skipped: 1



Parish Kitchen
35.20%




Holy Family Parish Master Plan

Soderstrom Architects

The existing gym has multiple problems that need addressing:a. The court is narrow and has little or no room for spectators.b. The interior and exterior paint shows moisture blisters from condensation. c. The roof to wall structural connections need to be evaluated.d. The locker rooms and restrooms do not meet ADA requirements.e. Access to the upper youth meeting rooms do not comply with ADA.f. The stairs to the upper youth meeting rooms do not comply with code.g. The hardwood floor is reaching its end of life.h. The building has no cooling or daylighting and the skylights are failing.The Gym building should be replaced with a new building.

Answered: 176 Skipped: 4



New Gym
60.80%




Holy Family Parish Master Plan

Soderstrom Architects

The Gym building should be repaired and youth spaces moved to another ADA accessible building.

Answered: 174 Skipped: 6



Repair Gym
51.15%




Holy Family Parish Master Plan

Soderstrom Architects

The gym is used by the School all day every day. The school children are walking back and forth between the school and the gym in inclement weather. Some form of covering should be designed to keep these kids from getting wet.

Answered: 177 Skipped: 3



Covered Walk
37.85%




Holy Family Parish Master Plan

Soderstrom Architects

The existing school was built in two phases. The north half was built in 1948 and the south half in 1956. Two modular classrooms were added in 1999. Phase 1 has no air conditioning and the boiler is well beyond its anticipated life span. Phase 2 HVAC is nearing the end of its life and showing serious rusting on the roof top equipment. All of the teaching spaces in the basement lack proper daylighting. We should fix the heating and cooling for the school.

Answered: 177 Skipped: 3



School HVAC
90.39%




Holy Family Parish Master Plan

Soderstrom Architects

Pre-school is becoming an important component of education. It is likely that the public schools will soon be required to support Pre-School. This is an important service to our parish community and an effective way to evangelize our neighborhood. Pre-school can be considered a revenue source as well. We should expand the pre-school offering and build the required pre-school facilities as part of the school expansion.

Answered: 177 Skipped: 3



School Expansion
61.01%




Holy Family Parish Master Plan

Soderstrom Architects

The Pre-K and Kindergarten are located in a modular building which are not connected to the existing school. These younger grades are constantly moving between the modular and the main building. They often get rained on. We should add classrooms to the main building to accommodate the Pre-K and Kinder classes.

Answered: 178 Skipped: 2



School Expansion
58.99%




Holy Family Parish Master Plan

Soderstrom Architects

The area allocated to the School “front office” secretarial area is too small for the function. Look for a way to expand the front office with waiting space, and transaction space.

Answered: 178 Skipped: 2



School Expansion
53.93%




Holy Family Parish Master Plan

Soderstrom Architects

The School library is currently in the basement. It has poor natural lighting and is small for a Pre-K thru 8 school. The School library should be expanded and moved to the upper level.

Answered: 176 Skipped: 4



School Expansion
43.75%




Holy Family Parish Master Plan

Soderstrom Architects

The existing school is not ADA accessible. In the past the school had a chair lift but it broke down frequently. The school should be made ADA accessible in a way that they can afford maintain it. Any building permit at the school will require that you spend 25% of the total construction costs on barrier removal.

Answered: 177 Skipped: 3



School ADA
74.58%




Holy Family Parish Master Plan

Soderstrom Architects

21st century education encourages hands on learning. Many elementary schools are providing dedicated space for science labs and maker spaces. Maker space includes things like robotics, 3d printing and other technical education. Holy Family should allow for these spaces in a future expansion of the School.

Answered: 177 Skipped: 3



21st Century School
70.06%




Holy Family Parish Master Plan

Soderstrom Architects

Although the existing church is relatively new; it was designed without a narthex (lobby). The noise from the lack of a lobby causes distraction during and after Mass. We should explore creating a sound barrier to control the noise. The lack of a narthex also makes it difficult to chat with friends after Mass. Building a parish hall could be part of the solution to the noise.

Answered: 176 Skipped: 4



Narthex Noise
50.00%




Holy Family Parish Master Plan

Soderstrom Architects


If the Parish offices are moved to another location we could sell the house east of the Parish offices and the Parish offices. We should sell these properties to help pay for needed expansion and repairs.

Answered: 174 Skipped: 6



Holy Family Parish Master Plan

Soderstrom Architects



Holy Family Parish Master Plan

Soderstrom Architects